A6013L

DIGITAL C METER OPERATION MANUAL

1.FEATURES

- \diamond Easy and correct readout.
- \diamond High measuring accuracy.
- Measurements are possible even under a strong magnetic field.
- ♦ LSI-circuit provides high reliability and durability.
- \diamond Input overload protection is provided.
- ♦ LCD display for low power consumption and clear readout even in bright ambient light conditions.
- \diamond In-line pushbuttons allow one hand operation.
- ♦ Light-weight and compact construction for easy operation.
- ♦ Low battery condition is indicated on the LCD display.

2.SPECIFICATIONS

2-1.GENERAL SPECIFICATIONS

:LCD (Liquid Crystal Display) Max Display Indication 1999. LCD Backlight and data hold. Measurement:C (Capacitance) single 9 position, whole range value (from Range 0.1pF to 20000uF) Zero Adjustment :Manual (range:±20pF) Calibrate Adjustment :Have two internal adjustment. One is panel Zero adjustment. Over-input :Display shows "1". Sampling Time :3/second Operating Temp :0°C to 40°C. Operating Humidity :80% MAX.R.H. Power Supply:Single, standard 9 volt battery. NEDA 1604IEC6F22

Battery Life : Alkaline type approx.: 200 hours.

Zinc-Carbon type approx.: 100 hours Typical consumption current :3~4mA (200pF-200uF) Standard Accessories: Test alligator clips (red & black)...1 pair.

Instruction manual.....1 pc.

2-2. ELECTRICAL SPECIFICATION

Accuracy is \pm (percentage of reading + number of digit)

at 23±5°C,<80%RH.				
Range	Accuracy	Resolution	Test	Max
200pF		0.1pF		199. 9pF
2nF		0.001nF		1.999nF
20nF		0.01nF	820Hz	19. 99nF
200nF	$\pm (0.5\% + 1d)$	0.1nF		199. 9nF
2uF		0.001uF		1.999uF
20uF		0.01uF	82Hz	19. 99uF
200uF		0.1uF		199. 9uF
2000uF	$\pm (2.0\% + 2d)$	1uF	8.2Hz	1999uF
20mF	$\pm (4.0\% + 10d)$	0.01mF		19.99mF

pF= Pico Farad(10^{-12} F), nF= nan Farad(10^{-9} F). uF= micro Farad(10^{-6} F)


Zero Error: ±20pF

Excitative voltage: Max.2.8Vrms

Overload Rating: Protection by a 0.2A/250V fuse.

2. Panel Layout

- LCD Display: 3¹/₂ digits, character
 15mm high
- ② Back Light Button Switch: Press this button to switch on back light if the dark circumstance light makes the reading



difficulty when measuring, the light will be automatically turned off in 5 seconds. Press again to switch it on again. If the battery is in weak power, the light will be dimmed.

- ③ Rotary Switch: use this switch to select ranges
- ④ "COM"Input Jack
- (5) (8)+" Input Jack (8)
- 6 Data-hold Switch (HOLD)
- ⑦ Zero ADJ.

3.CONSIDERATION OF MEASUREMENT

- (1) This C METER is intended for measuring the capacitance value of a capacitor. It is not intended for determining the "Q" factor for above reactive components. Misleading readings may be obtained if the measurement of capacitance of a resistor is attempted.
- (2) When measuring components within circuit that circuit must be switched off and de-energized before connecting the test leads.
- (3) Do not close (black & red) test leads.
- (4) Instruments used in dusty environments should be stripped and cleaned periodically.
- (5) Do not leave the instrument exposed to direct heat from the sun for long periods.
- (6) Before removing the battery and fuse compartment cover, ensure that the instrument is disconnected with any circuit and the power switch is in the off position.
- (7) For all measurements, should connect BLACK test lead into "-" terminal and RED test lead into "+" terminal.

4.CAPACITANCE(C) MEASURING PROCEDURE

- (1) Select the range switch for the maximum expected capacitance.
- (2) Check "0" indication: If test range is 200pF, 2nF, 20nF, should check "0" indication before test.
- (3) Observe polarity when connecting polarized capacitors.
- (4) Full discharge any capacitors.
- (5) Connect the alligator clips to the capacitors leads.
- (6) Read the display. The value is direct reading in the electrical unit (pF, nF, uF) indicated at the selected range switch. If display show "1", It indicate on Out-of-Range measurement. If the display indicates one or more leading zeros, shift to the next lower range scale to improve the resolution of the measurement.

NOTE:

- (a) If the capacitance value is unmarked, start from the 200pF range and keep increasing until the over-range indication goes off and a reading is obtained.
- (b) A shorted capacitor will read over-range on all ranges. A capacitance with low voltage leakage will read over range, or a much higher value than normal.

An open capacitor will read zero on all ranges (possibly a few pF on 200pF range, due to stray capacitance of the instrument).

- (c) Very low capacitance measurement should be performed by using extremely short leads in order to avoid introducing any stray inductance.
- (d) When using the optioned test leads, remember that the leads introduce a measurable capacitance to the measurement. As a first approximation, the test capacitance is measured by opening the leads at the trips, recording the open circuit value and subtracting that value.
- (e) Capacitors, especially electrolytic, often have notoriously wide tolerances. Do not be surprised if the measured value is greater than the value marked on the capacitor, unless it is a close tolerance type. However, value is seldom drastically below the rated value.
- (f) If changing range, measured value will be changed, leakage-voltage capacitors will be checked also. Leakage-resistance will be decreased in lower range.

5. MAINTENANCE

1) 9-Volt battery replacement

a. Ensure the instrument is not connected to any external circuit. Set the selector switch to

OFF position and remove the test leads from terminals.

- b. Remove the screw on the bottom case and lift the bottom case.
- c. Remove the spent battery and replace it with a battery of the same type.
- 2) Fuse replacement
- a. Ensure the instrument is not connected to any external circuit. Set the selector switch to

OFF position and remove the test leads from terminals.

- b. Remove the screw on the bottom case and lift the bottom case.
- c. Replace the fuse with the same type and rating: 5X20mm, 200mA/250V, fast-blow fuse or as the replacements.