

$$F = 1.18 / R_t \times C_t$$

$$F = 1 / ((0.7 \times R_T + 3 \times R_D) \times C_t)$$

TITLE: SG3525-500W-SMPS

Document Number:

REV:

Date: 9.7.2017. 21:43:24

Sheet: 1/1

